

```
l 10.710941] hub 1-1:1.0: 6 ports detected
l 10.712148] usb 3-1: new high-speed USB device number 2 using ehci-pci
l 10.744721] usb 3-1: New USB device found, idVendor=8087, idProduct=0024, bcdDevice= 0.00
l 10.745399] usb 3-1: New USB device strings: Mfr=0, Product=0, SerialNumber=0
l 10.746149] hub 3-1:1.0: USB hub found
l 10.746808] hub 3-1:1.0: 8 ports detected
l 10.839398] nouveau 0000:0a:00.0: bios: version 70.10.75.00.04
l 10.862438] nouveau 0000:0a:00.0: fb: 2048 MiB GDDR5
l 10.935570] [TTM] Zone kernel: Available graphics memory: 6611342 KiB
l 10.935801] [TTM] Zone dma32: Available graphics memory: 2097152 KiB
l 10.936026] [TTM] Initializing pool allocator
l 10.936274] [TTM] Initializing DMA pool allocator
l 10.936511] nouveau 0000:0a:00.0: DRM: VRAM: 2048 MiB
l 10.936730] nouveau 0000:0a:00.0: DRM: GART: 1048576 MiB
l 10.936950] nouveau 0000:0a:00.0: DRM: TMDS table version 2.0
l 10.937171] nouveau 0000:0a:00.0: DRM: DCB version 4.0
l 10.937390] nouveau 0000:0a:00.0: DRM: DCB outp 00: 02000300 00000000
l 10.937615] nouveau 0000:0a:00.0: DRM: DCB outp 01: 01000302 00020030
l 10.937839] nouveau 0000:0a:00.0: DRM: DCB outp 02: 048113b6 0f220010
l 10.938064] nouveau 0000:0a:00.0: DRM: DCB outp 03: 04011372 00020010
l 10.938288] nouveau 0000:0a:00.0: DRM: DCB outp 04: 028223a6 0f220010
l 10.938513] nouveau 0000:0a:00.0: DRM: DCB outp 05: 02022362 00020010
l 10.938737] nouveau 0000:0a:00.0: DRM: DCB conn 00: 00001030
l 10.938958] nouveau 0000:0a:00.0: DRM: DCB conn 01: 00410146
l 10.939179] nouveau 0000:0a:00.0: DRM: DCB conn 02: 00202246
l 10.939400] nouveau 0000:0a:00.0: DRM: DCB conn 03: 00000360
l 10.941610] nouveau 0000:0a:00.0: DRM: MM: using COPY1 for buffer copies
l 10.944214] [drm] Supports vblank timestamp caching Rev 2 (21.10.2013).
l 10.944443] [drm] Driver supports precise vblank timestamp query.
l 10.964673] ata3: SATA link down (SStatus 0 SControl 300)
l 11.000182] usb 1-1.3: new full-speed USB device number 3 using ehci-pci
l 11.036151] usb 3-1.3: new high-speed USB device number 3 using ehci-pci
l 11.064633] usb 3-1.3: New USB device found, idVendor=0424, idProduct=2660, bcdDevice= 8.01
l 11.065020] usb 3-1.3: New USB device strings: Mfr=0, Product=0, SerialNumber=0
l 11.065778] hub 3-1.3:1.0: USB hub found
l 11.066190] hub 3-1.3:1.0: 2 ports detected
l 11.158647] nouveau 0000:0a:00.0: DRM: allocated 1920x1080 fb: 0x60000, bo 00000000c452f9d7
l 11.176308] fbcon: nouveaudrmfb (fb0) is primary device
l 11.264412] ata1.00: SATA link down (SStatus 0 SControl 300)
l 11.264458] ata1.01: SATA link up 1.5 Gbps (SStatus 113 SControl 300)
l 11.280583] ata1.01: ATAPI: hp DVD-ROM SH-116AB, JH00, max UDMA/100
l 11.285696] ata1.01: configured for UDMA/100
l 11.288137] scsi 1:0:1:0: CD-ROM hp DVD-ROM SH-116AB JH00 PQ: 0 ANSI: 5
l 11.312198] usb 1-1.3: device descriptor read/64, error -32
l 11.332565] Console: switching to colour frame buffer device 240x67
l 11.413835] scsi 1:0:1:0: Attached scsi generic sg4 type 5
l 11.458460] nouveau 0000:0a:00.0: fb0: nouveaudrmfb frame buffer device
l 11.486751] EXT4-fs (sda3): mounted filesystem with ordered data mode. Opts: acl,user_xattr
l 11.488744] [drm] Initialized nouveau 1.3.1 20120801 for 0000:0a:00.0 on minor 0
```

Dmesg with quadro 4000

```
l 10.715602] hub 1-1:1.0: USB hub found
l 10.715845] hub 1-1:1.0: 6 ports detected
l 10.742968] usb 3-1: New USB device found, idVendor=8087, idProduct=0024, bcdDevice= 0.00
l 10.743238] usb 3-1: New USB device strings: Mfr=0, Product=0, SerialNumber=0
l 10.743754] hub 3-1:1.0: USB hub found
l 10.744094] hub 3-1:1.0: 8 ports detected
l 10.780983] nouveau 0000:0a:00.0: bios: version 80.04.fe.00.07
l 10.782276] nouveau 0000:0a:00.0: fb: 4096 MiB GDDR5
l 10.874902] [TTM] Zone kernel: Available graphics memory: 6611342 KiB
l 10.875090] [TTM] Zone dma32: Available graphics memory: 2097152 KiB
l 10.875266] [TTM] Initializing pool allocator
l 10.875450] [TTM] Initializing DMA pool allocator
l 10.875658] nouveau 0000:0a:00.0: DRM: VRAM: 4096 MiB
l 10.875833] nouveau 0000:0a:00.0: DRM: GART: 1048576 MiB
l 10.876009] nouveau 0000:0a:00.0: DRM: TMDS table version 2.0
l 10.876185] nouveau 0000:0a:00.0: DRM: DCB version 4.0
l 10.876358] nouveau 0000:0a:00.0: DRM: DCB outp 00: 01000f02 00020030
l 10.876537] nouveau 0000:0a:00.0: DRM: DCB outp 01: 02000f00 00000000
l 10.876714] nouveau 0000:0a:00.0: DRM: DCB outp 03: 02822fa6 0f420010
l 10.876889] nouveau 0000:0a:00.0: DRM: DCB outp 04: 02022f62 00020010
l 10.877064] nouveau 0000:0a:00.0: DRM: DCB outp 05: 04833fb6 0f420010
l 10.877240] nouveau 0000:0a:00.0: DRM: DCB outp 06: 04033f72 00020010
l 10.877417] nouveau 0000:0a:00.0: DRM: DCB conn 00: 00001030
l 10.877591] nouveau 0000:0a:00.0: DRM: DCB conn 02: 00002246
l 10.877764] nouveau 0000:0a:00.0: DRM: DCB conn 03: 00010346
l 10.877938] nouveau 0000:0a:00.0: DRM: DCB conn 04: 00000460
l 10.881988] nouveau 0000:0a:00.0: DRM: MM: using COPY for buffer copies
l 10.906277] [drm] Supports vblank timestamp caching Rev 2 (21.10.2013).
l 10.906483] [drm] Driver supports precise vblank timestamp query.
l 10.961003] ata3: SATA link down (SStatus 0 SControl 300)
l 11.002200] usb 1-1.3: new low-speed USB device number 3 using ehci-pci
l 11.034200] usb 3-1.3: new high-speed USB device number 3 using ehci-pci
l 11.062764] usb 3-1.3: New USB device found, idVendor=0424, idProduct=2660, bcdDevice= 8.01
l 11.062993] usb 3-1.3: New USB device strings: Mfr=0, Product=0, SerialNumber=0
l 11.063717] hub 3-1.3:1.0: USB hub found
l 11.063987] hub 3-1.3:1.0: 2 ports detected
l 11.090172] nouveau 0000:0a:00.0: DRM: allocated 1920x1080 fb: 0xa0000, bo 00000000b993ed47
l 11.091592] fbcon: nouveaudrmfb (fb0) is primary device
l 11.114963] usb 1-1.3: New USB device found, idVendor=093a, idProduct=2510, bcdDevice= 1.00
l 11.114966] usb 1-1.3: New USB device strings: Mfr=1, Product=2, SerialNumber=0
l 11.114968] usb 1-1.3: Product: USB Optical Mouse
l 11.114969] usb 1-1.3: Manufacturer: PixArt
l 11.128009] usbcore: registered new interface driver usbhid
l 11.128010] usbhid: USB HID core driver
l 11.133186] input: PixArt USB Optical Mouse as /devices/pci0000:00/0000:00:1a.0/usb1/1-1/1-1.3/1-1.3:1.0/0003:093A:2510.0001
l 11.134061] hid-generic 0003:093A:2510.0001: input,hidraw0: USB HID v1.11 Mouse [PixArt USB Optical Mouse] on usb-0000:00:1a
l 11.194174] usb 1-1.4: new low-speed USB device number 4 using ehci-pci
l 11.262406] ata1.00: SATA link down (SStatus 0 SControl 300)
l 11.262469] ata1.01: SATA link up 1.5 Gbps (SStatus 113 SControl 300)
l 11.280465] ata1.01: ATAPI: hp DVD-ROM SH-116AB, JH00, max UDMA/100
l 11.285744] nouveau 0000:0a:00.0: disp: outp 03:0006:0f42: training failed
l 11.317985] usb 1-1.4: New USB device found, idVendor=03f0, idProduct=0024, bcdDevice= 1.30
l 11.317990] usb 1-1.4: New USB device strings: Mfr=1, Product=2, SerialNumber=0
l 11.317993] usb 1-1.4: Product: HP Basic USB Keyboard
l 11.317995] usb 1-1.4: Manufacturer: CHICONY
l 11.322649] ata1.01: configured for UDMA/100
l 11.327782] input: CHICONY HP Basic USB Keyboard as /devices/pci0000:00/0000:00:1a.0/usb1/1-1/1-1.4/1-1.4:1.0/0003:03F0:0024
l 11.339704] scsi 1:0:1:0: CD-ROM hp DVD-ROM SH-116AB JH00 PQ: 0 ANSI: 5
l 11.386616] hid-generic 0003:03F0:0024.0002: input,hidraw1: USB HID v1.11 Keyboard [CHICONY HP Basic USB Keyboard] on usb-00
l 11.436542] scsi 1:0:1:0: Attached scsi generic sg4 type 5
l 11.439070] Console: switching to colour frame buffer device 240x67
l 11.440475] nouveau 0000:0a:00.0: fb0: nouveaudrmfb frame buffer device
l 11.466200] usb 1-1.5: new full-speed USB device number 5 using ehci-pci
l 11.490896] [drm] Initialized nouveau 1.3.1 20120801 for 0000:0a:00.0 on minor 0
```

Dmesg with Quadro K420